



# **GROUNDWATER QUALITY ANALYSIS REPORT**


## ***Kampong Cham - Kaoh Soutin - Moha Khnhoung (N/A)***



Moha Khnhoung is located in the district of Kaoh Soutin. The population of this commune is approximately 7913 (2004). Groundwater sample collection occurred in July 2008 and consisted of the sampling of 4 tube wells throughout the commune. The attached figure presents the location of Moha Khnhoung within Kampong Cham as well as groundwater sample locations and exceedances of health-impacting contaminants (when applicable).








### **Groundwater Quality Rating**

An insufficient number of samples were collected in this commune to adequately characterize groundwater conditions. A groundwater quality rating is not presented for this commune.



## Tube Well Sample Locations and Health-Based Exceedances

*Moha Khnhoung - Kaoh Soutin - Kampong Cham - Cambodia*

-  No Exceedance
-  Arsenic
-  Manganese
-  Fluoride
-  Nitrate
-  Commune Boundary
-  Provincial Boundary
- Locations exceeding the Cambodian water quality standards for major health-impacting contaminants have been colour-coded and arranged such that they do not overlap.

Resource Development International - Cambodia  
[www.rdic.org](http://www.rdic.org)  
 June 2008

