




GROUNDWATER QUALITY ANALYSIS REPORT


Kampong Cham - Tboung Khmum - Chirou Muoy (N/A)



Chirou Muoy is located in the district of Tboung Khmum. The population of this commune is approximately 5988 (2004). Groundwater sample collection occurred in June 2008 and consisted of the sampling of 1 tube wells throughout the commune. The attached figure presents the location of Chirou Muoy within Kampong Cham as well as groundwater sample locations and exceedances of health-impacting contaminants (when applicable).

Groundwater Quality Rating

An insufficient number of samples were collected in this commune to adequately characterize groundwater conditions. A groundwater quality rating is not presented for this commune.



Tube Well Sample Locations and Health-Based Exceedances

Chirou Muoy - Tboung Khmum - Kampong Cham - Cambodia

Resource Development International - Cambodia

www.rdic.org

June 2008



Locations exceeding the Cambodian water quality standards for major health-impacting contaminants have been colour-coded and arranged such that they do not overlap.

-  No Exceedance
-  Arsenic
-  Manganese
-  Fluoride
-  Nitrate
-  Commune Boundary
-  Provincial Boundary